

寸切 S45C(H)

L	D	M12	M16
30		○	○
35		○	○
40		○	○
45		○	○
50		○	○
55		○	○
60		○	○
65		○	○
70		○	○
75		○	○
80		○	○
85		○	○
90		○	○
95		○	○
100		○	○
105		○	○
110		○	○
115		○	○
120		○	○
125		○	○
130		○	○
135		○	○
140		○	○
145		○	○
150		○	○
155		○	○
160		○	○
165		○	○
170		○	○
175		○	○
180		○	○
185		○	○
190		○	○
195		○	○
200		○	○

L	D	M12	M16
210		○	○
220		○	○
230		○	○
240		○	○
250		○	○
260		○	○
270		○	○
280		○	○
290		○	○
300		○	○
310		○	○
320		○	○
330		○	○
340		○	○
350		○	○
360		○	○
370		○	○
380		○	○
390		○	○
400		○	○
410		○	○
420		○	○
430		○	○
440		○	○
450		○	○
460		○	○
470		○	○
480		○	○
490		○	○
500		○	○

D	L	1000	2000
M12		○	○
M16		○	○
M20		○	○
M22		○	○
M24		○	○
M27		○	○
M30		○	○